

SURVEY & REMONUMENTATION

OCT 11 1994

COMMISSION

MACKINAC COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac
(County)

Located In:

Corner Code #

RECEIVED & FILED
DIANE FRANKOVICH
MACKINAC COUNTY REGISTER OF DEEDS

SEP 6 1994

AM 7/8/9/10/11/12/1/2/3/4/5/6 PM

Register of Deeds Stamp & File Number

1. Public Land Survey

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

#9

4. Lot No. , Recorded Plat

5. Private Claims ~~Where the N-S Section line between Sections 15~~
& 14 intersects the West line of Private Claims, T40N
R04W, Moran Township. I-7/I-6
Neil E. Hill August 22 94

I, , in a field survey on , 19
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Set post at 28.30 ch North of I-7
Tied 6" Cedar S24W 0.22 ch
12" Birch S14E 0.19 ch

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No records of corner
Feindt surveys in the area
Found 1 1/4" pipe at corner location
5" Balsam S25W 18.70' (face)
5" Balsam N15E 19.60' (face)
4" Balsam N75W 18.80' (face)

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 8-16-94

James H. Kranger

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted 1 1/4" pipe; placed 5/8" re-rod inside of pipe with 4" aluminum cap.
5" Balsam S25W 19.20' (nail in side)
5" Balsam N25E 19.64' (nail in side)
4" Balsam N50W 19.20' (nail in side)
6" Balsam S60W 17.86'



Signed by Neil E. Hill P.S. Date August 22, 1994

Surveyor's Michigan License No. 27447

D-0282