

SURVEY &
REMONUMENTATION

MAY 20 1997

**MACKINAC COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 40N R 4W

P.C.C. #1

NW Cor. P.C. #1

2. Property Controlling
in Section

S _____ T _____ R _____
S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

RECEIVED & FILED
DIANE FRANKOVICH
MACKINAC COUNTY REGISTER OF DEEDS

NOV 15 1996
AM _____ PM _____
7|8|9|10|11|12|1|2|3|4|5|6

Register of Deeds Stamp & File Number

I, Neil E. Hill, in a field survey on SEPTEMBER 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO from NE Corner of lake measured S81W 230.00 chains, set post to Claims 1 & 2

5" Cedar N20E 15 lks

5" Tamarack S16E 16 lks

Various surveys, most recent Charlevoix A&E 1976. (not recorded)

See sketch on reverse of P.C.C. #6.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found corner at angle point in West Claim Line, S09E and line N33W.

8"x8" square concrete monument with chis "X" flush with ground. Found 5' high squared post next to corner, along East edge of power line.

3" Hemlock North 7.35'

6" Cedar S25E 15.10' (face)

3" Spruce N65E 14.45'

Accepted corner location.

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 9-30-96

James H. Granger



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is 8"x8" square concrete monument with chis. "X" flush with ground, a 5' high squared post is next to corner, along East edge of power line.

5" Balsam N10E 12.66'

4" Cedar N30E 10.50'

4" Balsam N65E 8.06'

6" Cedar S70E 15.19' (side)

Signed by Neil E. Hill S.S., P.C. Date SEPTEMBER 30, 1996

27447

Surveyor's Michigan License No. _____