

SURVEY & REMONUMENTATION

MAY 20 1997

COMMISSION

MACKINAC COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac
(County)

Located In:

Corner Code ##

1. Public Land Survey

T40N R4W

P.C.C. #2

T R

NW Cor. P.C. #2

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

#26

RECEIVED & FILED
DIANE FRANKOVICH
MACKINAC COUNTY REGIST. OF DEEDS

NOV 15 1996

AM 7 PM 16
7|8|9|10|11|12|1|2|3|4|5|6

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Neil E. Hill, in a field survey on SEPTEMBER 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO N33W 10.24 chains (675.84 feet). Set post.

7" Cedar N83E 14 lks

6" Cedar N13W 15 lks

Various surveys, most recent Charlevoix A&E 1976. (Not recorded)

See sketch on reverse of P.C.C. #6.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found corner. 3/4" pipe with cap #3920 flush with ground. Fence post 3' East of corner along East edge of power line.

4" Spruce S40E 18.20'

3" Cedar North 13.60'

3" Spruce N42E 11.97'

Accepted corner location.

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 9-30-96

James H. Kravger



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted corner in place.

3/4" pipe with cap #3920 flush with ground. Fence post 3' East of corner along East edge of power line

16" Cedar N30W 40.71'

4" Spruce N50E 13.10'

6" Balsam East 8.20'

8" Balsam S40E 18.41'

Signed by Neil E. Hill P.S., P.C. Date SEPTEMBER 30, 1996

Surveyor's Michigan License No. 27447