

MAY 20 1997

COMMISSION

MACKINAC COUNTY REMONUMENTATION CORNER  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac  
(County)

Located In:

Corner Code ##

- 1. Public Land Survey
- 2. Property Controlling in Section
- 3. Miscellaneous Property in Sec.

T 40N R 4W  
T R  
T R  
T R  
S T R  
S T R  
S T R  
S T R

P.P.C. #3  
NW Cor PC #3  
#27

RECEIVED & FILED  
DIANE FRANKOVICH  
MACKINAC COUNTY REGISTRE OF DEEDS

NOV 15 1996  
AM PM  
7|8|9|10|11|12|1|2|3|4|5|6

Register of Deeds Stamp & File Number

- 4. Lot No. , Recorded Plat
- 5. Private Claims

I, Neil E. Hill, in a field survey on SEPTEMBER 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO notes. From Lake Huron S80W 229.30 ch. Set post intersect 1.21 chains from SW corner PC #3 (79.86 feet).  
10" Birch N09W 14 lks  
3" Fir S02E 06 lks  
Various surveys, most recent Charlevoix A&E 1976.  
See sketch on reverse of P.C.C. #6.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found corner. 3/4" pipe with cap #3920 flush with ground along East edge of power line.  
PP East 60.08' (face)  
6" Birch S29W 8.00'  
3" Balsam N51W 14.00'  
Accepted corner location.

ACCEPTED BY THE MACKINAC COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER P.A.  
345 OF 1990 AT A MEETING  
HELD ON 9-30-96

James H. Granger

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted corner in place.  
3/4" pipe with cap #3920 flush with ground, along East edge of power line  
PP West 60.70' (side)  
8" Birch N10E 5.82'  
4" Balsam S35E 16.63'  
16" Balsam S30E 39.40'



Signed by Neil E. Hill P.S., P.C. Date SEPTEMBER 30, 1996  
Surveyor's Michigan License No. 27447