

MAY 26 1997

COMMISSION

**MACKINAC COUNTY REMONUMENTATION CORNER**  
**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac  
(County)

Located In:

Corner Code #

**RECEIVED & FILED**  
**DIANE FRANKOVICH**  
MACKINAC COUNTY REGISTER OF DEEDS

NOV 7 1996

AM PM  
7/8/9/10/11/12/1/2/3/4/5/6

Register of Deeds Stamp & File Number

1. Public Land Survey T 40N R 4W  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

P.C.C. #4  
NW Corner P.C. #4

#28

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Neil E. Hill, in a field survey on SEPTEMBER 30, 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A: Description of original monument and accessories and/or subsequent restoration:

GLO notes N33W 6.50 ch (429.00 feet). Set post

7" Birch N33W 20 lks

9" Wood S60E 07 lks

Various surveys. Most recent by Charlevoix A&E 1976. (Not recorded)

See sketch on reverse of P.C.C. #6.

B: Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found corner. 3/4" pipe 18" high next to 2" x 2" old scribed wood post 1' West of fence post along East edge of power line.

8" Cedar N15W 37.00'

10" Cedar East 6.10'

P. Pole N75W 71.75' (face)

Accepted location.

ACCEPTED BY THE MACKINAC COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER P.A.  
345 OF 1990 AT A MEETING  
HELD ON 9-30-96

*James H. Granger*

C: Description of monument for corner and accessories established to perpetuate locating the position of the corner:


Replaced with 5/8" rerod and aluminum cap. 1' West of fence post along East edge of power line.

4" Cedar N50E 6.20'

18" Cedar S75E 6.20'

8" Cedar S50E 9.57'

3" Cedar S35E 3.36'



Signed by Neil E. Hill P.S., P.C. Date SEPTEMBER 30, 1996

Surveyor's Michigan License No. 27447