

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Mackinac Co.

two corners

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY-----	T. <u>41</u> N. R. <u>11</u> E.	<u>F-3</u> 1, Sec. 9
2. PROPERTY CONTROLLING IN SECTION <u>9</u>	T. <u>41</u> N. R. <u>11</u> E.	
3. MISCELLANEOUS PROPERTY IN SECTION-----	T.----- N. S. R.----- E. W.	
4. LOT NO.-----, RECORDED PLAT-----		
5. PRIVATE CLAIMS-----		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 4/6 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

F-3 Original  $\frac{1}{4}$  Cor. set by John Burt, D.S., Aug. 1845.  
Bearings were:

W. Pine 6" N90E 60 Links  
W. Pine 4" S30W 39 Links

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-3 Found an old squared post, set by unknown surveyor: Found no evidence of original witnesses, but found Cedars blazed as witnesses.

1, Sec. 9 Placed  $\frac{1}{16}$  Cor. midway and on line bet. two Cors. Found a wood post, 1.0' East; also an Iron Fence Post, 5.0' East and 6.0' South of Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 1" iron pipe with 4" aluminum cap at both corners.

F-3 Bearings:

12" W. Pine S48E 55.3'  
8" Cedar N15E 65.2'

1, Sec. 9 Bearings:

8" Cedar N28E 16.4'  
7" Cedar N50W 14.6'

SIGNED BY Billy D. Buckler

DATE 6/14/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_