

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Mackinac COUNTY
T 41N R 11 W

DESCRIPTION OF CORNER 1/4 Corner bet. Secs. 8-9

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9-18-69

WITNESSES TO CORNER..... 10" Hard Maple (1/8 NBT) S43°E 27.1'



10" Hard Maple, Twin (1/8 NBT) S60W 70.0'

12" W. Birch (1/8 NBT) N61°E 15.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as marked by an unknown surveyor. Found remains of two Balsam stumps with bearing blazes, facing position of corner; S6°W, 9.5' and S71°E 16.0', both marks are very old, tho not old enough to be original.

Corner lies 4.0' East of an old logging road.

Found old blazes on trees, South to the lake.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

Billy D. Buckler

DATE

9-28-71

REGISTERED LAND SURVEYOR

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing