

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Mackinac  
(County)

Located In:

Corner Code #

- |                                    |   |            |   |           |            |
|------------------------------------|---|------------|---|-----------|------------|
| 1. Public Land Survey              | T | <u>41N</u> | R | <u>4W</u> | <u>G-1</u> |
|                                    | T |            | R |           |            |
|                                    | T |            | R |           |            |
|                                    | T |            | R |           |            |
| 2. Property Controlling in Section | S |            | T |           | R          |
|                                    | S |            | T |           | R          |
| 3. Miscellaneous                   | S |            | T |           | R          |
| Property in Section                | S |            | T |           | R          |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, David B. Guthrie in a field survey on April 17, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

## A. Description of original monument and accessories and/or subsequent restoration:

1845: G.L.O. Survey by J.A. Mullett - Set Post and Referenced  
 Sugar 18 - S26W - 50

1957: Survey by MDOT - 1 1/4" Iron Pin

1986: Survey by MDOT - Set 1/2" Iron Rod 33 feet East of 1 1/4" Iron Pin.  
 Believed MDOT found standard corner in 1957 (1 1/4" Iron Pin).

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1996: Found 1/2" Iron Rod 33 Feet East of 1 1/4" Iron Pin.

**SURVEY &  
 REMONUMENTATION**

MAY 20 1997

**COMMISSION**

ACCEPTED BY THE MACKINAC COUNTY  
 SURVEY PEER GROUP AS THE  
 OFFICIAL CORNER UNDER P.A.  
 345 OF 1990 AT A MEETING  
 HELD ON B-20-96

*James H. Granger*

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1996: Placed an Aluminum Cap stamped to identify the corner on a 5/8" Iron Rod.

Referenced: S40°W - Fe. Cor. - 43.46 Feet  
 S59°W - Utility Pole - 57.30 Feet  
 S20°E - 16" Maple - 95.20 Feet  
 N75°E - 10" R. Pine - 56.83 Feet  
 West - 1 1/4" Iron Pin - 33.00 Feet



Signed by

*David B. Guthrie*

Date

Oct. 2, 1996

Surveyor's Michigan License No. 22435

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN., 1983