SURVEY & REMONUMENTATION

OCT 1 1 1994 COMMISSION

Surveyor's Michigan License No. 16041

MACKINAC COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	•	•		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	v 0 9 8 8 8 8 8
Mackinac (County)	Located In:	Corner Code =#1			
Public Land Survey	T 42N R 1W T R T R T R	A-3	_	ONP (5 1994 574
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R				Stamp & File Number
4. Lot No , F	Recorded Plat			- A B C D	E F G H I J K
5. Private Claims				2 5 5	
	in a field supply on August	+ 0 10	o 0 <i>4</i>	3 4 7 8	91011
do hereby certify that under re- in lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance wi Court of Law; established, expressed below:	, in a field survey onAugus: quirements of P.A. 74, Michigan P.A n conformance with regulations a ructions of the United States Depa a Court of Law and/or that the corn the the rules of the Michigan Board re-established, monumented, re-	A. of 1970, the corner points and rules therefore as requartment of the Interior, Burder points mentioned in line of Land Surveyors or by a -monumented, recovered	s mentioned uired in the eau of Land es 3, 4 and 5 Decree of a I, found as	5 61817 7 81920 9	21 22 23 23 24 27 26 26 27 26 26 27
NOTE: Not more than 4 corners, all in the same town and range, on this certificate.		and range, may be reco	orded 	11 31 32	33 34 35
A. Description of original	monument and accessories ar	nd/or subsequent resto	ration;		
1840 original sur William Burt	10" cedar	t S30°W 321ks. N20°W 271ks.			
1980 USFS Harold Stockholm #23519	set 2 1/2" p set 5 witnes	ipe w/brass cap ses			
B. Description of corner e	evidence found and/or method	applied in restoring or	reestablishing	corner:	
Found USFS monum	ent and 3 witnesses				
		1	SURVEY F OFFICIAL	D BY THE MACKIN PEER GROUP AS T CORNER UNDER I 90 AT A MEETING 10 - 16 - 9	HE P.A.
09-06-94			Jan	MH DE	
C. Description of monume	ent for corner and accessories e w/brass cap	established to perpetu	_	of Michigan	corner:
8" birch S2 11" cedar N5 11" cedar S5	rth 3' 5°W 7.09' Stockho 0°W 22.60' Stockho 6°E 34.76' Stockho 7°E 23.60' tag #10	olm tag olm tag	* FICE	GRANGER	A BOA

D-0295

August 30, 1994

-09-05-94 form Approved by michigan state board of Land surveyors, Can. 28. 1971 Revised May 14, 1975 Revised Jan., 1983