

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 42N N.R. 6W


Mackinac COUNTY

DESCRIPTION OF CORNER South 1/8 corner between sections 17-18

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 5-2-62

WITNESSES TO CORNER..... 8" Beech (BT) N34°E, 11 links



8" Beech (BT) N85°W, 05 links

M.S.H.D. ROW Monument S1°W, 72 links

AND M.S.H.D. ROW Monument N83°W, 83 links

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway between section corner to south and 1/4 corner to north.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 29, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler