

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>42</u> N. <u>X</u> , R. <u>6</u> W.	<u>C-1</u>
2. PROPERTY CONTROLL- ING IN SECTION_____	T. _____ N. _____ S., R. _____ E. _____ W.	
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. _____ S., R. _____ E. _____ W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7/25, 1977, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

C-1 Closing Corner bet. Sec's. 5-6, on North Twp. line, set by Deputy Surveyor during sub-division of T42N R6W. Bearings were: Balsam 8", S48°E, 18 lks. and Balsam 8", S58°W, 18 lks.


B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-1 Found old wood post in ground with a 15" Cedar bearing S67°W, 19.4'. Tree is dead and fallen; was marked 30 years before it died. Scribe marks (R6W, T42N, S6) on upper face. Lower marks is apparent but grown over. Did not chop this out.  
NOTE: This corner lies 18.5' West of standard corner, Sections 31-32, T43N R6W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1 Placed 1" pipe with 4" aluminum cap at corner.  
New Bearings: 10" Cedar, ( S6 C.C. NBT ) S54°W, 40.3'.  
8" Cedar, ( S6 C.C. NBT ) S10°W, 37.4'.  
5" Cedar, ( S5 C.C. NBT ) S60°E, 3.2'.

SIGNED BY Billy D. Buckler DATE 9/20/77  
Billy D. Buckler  
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY  
APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_