

SURVEY & REMONUMENTATION

MAR 13 1998

MACKINAC COUNTY REMONUMENTATION CORNER

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Mackinac
(County)

Located In:

Corner Code #

1. Public Land Survey

T42N R3W

MC M6/M7 #4

T42N R2W

Section 13

T R

MC A6/A7 #1

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Neile E. Hill, in a field survey on DEC. 22, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1840 GLO notes William Burt 6" Aspen S79E 13 lks
GLO distance 2121.90' South of 1/4 Corner 7" Cedar N14W 10 lks

No records of this corner being perpetuated, however a survey by R. Bisler indicated a position for this corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997 No evidence of corner. Set at GLO position of 2121.90' South of 1/4 Corner.
Found 1/2" iron 466.20' further South of GLO MC, also witness this location.

ACCEPTED BY THE MACKINAC COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-21-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Witness to point at lake 1/2" rerod.

8" Cedar N10W 63.44'
14" Cedar N20E 34.28'
8" Cedar East 10.04'
8" Cedar S80E 16.93'

Witness to MC 1/2" rerod with remonumentation cap

6" Cedar N80E 07.97'
14" Cedar S45E 17.55'
8" Cedar S30W 07.41'
8" Cedar Due West 08.29'

Signed by Neile E. Hill P.S.
Surveyor's Michigan License No. 27447

Date DECEMBER 22, 1997

