

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 8W


Mackinac COUNTY

DESCRIPTION OF CORNER N 1/16 Corner, Sec. 3

CORNER MONUMENT 5/8" Iron Bar, buried in west side of road.

DATE MONUMENT PLACED AND WITNESSED 6/68

WITNESSES TO CORNER..... 11" Hard Maple (NBT) S85°W 15.8'



5" Hard Maple (NBT) S78°E 28.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as set by D.A. Brotherton, Land Surveyor about 1916.  
Determined location from other corners in Sec. and from an old set of maps by  
Brotherton, showing the Mackinac County trunkline roads of date 1916.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler, R.L.S. DATE 10-8-68  
REGISTERED LAND SURVEYOR