

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Mackinac</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 20 T 43N R 10W	15
	S 20 T 43N R 10W	16
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4		3		2		1
3													
4	7			8			9		10		11		12
5													
6	18			17			16		15		14		13
7													
8	19			20			21		22		23		24
9													
10	30			29			28		27		26		25
11													
12	31			32			33		34		35		36
13													

I, Stephan J. Szyszkoski, in a field survey on 15 09/30/2009 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 20) West 1/16 corner between Sections 20 and 29. Not established in the original survey.

(16-Sec. 20) East 1/16 corner between Sections 20 and 29. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 20) Established the corner midway and on the Section line between Section corner 1295.02'
west and Quarter corner 1295.02' east. The position for the corner falls in the traveled surface of
Hwy. US-2 and was not monumented. Established a witness corner at the intersection of the West N-S
1/16 line with the northerly R/W line of US-2 249.34' north of the corner position.

(16-Sec. 20) Established the corner midway and on the Section line between Section corner 1312.65'
east and Quarter corner 1312.65' west. The position for the corner falls in the traveled surface of
Hwy. US-2 and was not monumented. Established a witness corner at the intersection of the East N-S
1/16 line with the northerly R/W line of US-2 221.50' north of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx36" I.pipe with 4" alum. MDNR cap
stamped "WC W1/16 20/29 249.34' S"
Set measuring nail with MDNR tag in the side of:
9" Cedar N10E 11.47' mrkd "WC BT"
9" Cedar S80W 5.03' do
14" Maple N56E 7.74' do
14" Cedar S73E 63.78' do
Bearings are magnetic.

(16) Set 1"IDx36" I.pipe with 4" alum. MDNR cap
stamped "WC E1/16 20/29 221.50' S"
Set measuring nail with MDNR tag in the side of:
7" Cedar S57W 31.45' mrkd "WC BT"
11" Tamarack N70W 23.0' do
6" Cedar N09W 21.78' do
5" Cedar S84E 21.16' do
Bearings are magnetic.

Signed by

Stephan J. Szyszkoski

Date

10/13/2009

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

