

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 43N R 11W-12W

DESCRIPTION OF CORNER Sec. Cor. common to Secs'. 18-19-13-24

CORNER MONUMENT 1" Axle Shaft

DATE MONUMENT PLACED AND WITNESSED 5/20/71

WITNESSES TO CORNER..... 9" Cedar (S24 NBT) S36°W 10.9'



8" Cedar (S19 NBT) S75°E 17.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner witnessed as set by unknown surveyor.

Found remains of original witness in proper position as well as several old blazes at the corner.

Checked distance south to stream.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE 2/17/72

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing ✓

R 4047
Rev. 10/68