

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N. R. 7W


Mackinac COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ corner for sections 28-29

CORNER MONUMENT 1" pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED 7-24-61

WITNESSES TO CORNER..... 10" Apple (NBT) S42°W 111 links



16" W. Pine ($\frac{1}{4}$ S NBT) N45°E 161 $\frac{1}{2}$ links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between section corners. Position checks with swamp edge 1.50 chs. north.
Corner lies 53 links north of road and in line with fence to east. Found old N-S
Fence 36 links east.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 13, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler