

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>44</u> N. <u>7</u> R. <u>7</u> E. <u>W.</u>	<u>L-9, K-9</u>
2. PROPERTY CONTROLLING IN SECTION <u>22</u>	T. <u>44</u> N. <u>7</u> R. <u>7</u> E. <u>W.</u>	<u>3</u>
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Gerald L. Wiggins, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-10-87, 1987, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 8-10-87, 1987, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- L-9 South 1/4 Corner of Section 24. Set by Billy D. Buckler L.S. on 9-28-79. NBT'S:
7" Tamarack, S31°W, 24.2' & 8" Cedar, N5°W, 10.3' & 6" Cedar, S76°E, 13.7'.
- K-9 N.W. Section Corner of Section 25. Set by Billy D. Buckler, L.S. on 9-29-87. NBT'S:
No witnesses available.
- 3 North 1/16 Corner on the West side of Section 22. Set by Billy D. Buckler, L.S. on 4-29-81.
BT'S: 8" Cedar, S40°W, 15.4' & 7" Cedar, N35°W, 18.8' & 6" Cedar, N65°E, 36.1'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Rewitnessed all three corners as set by Billy D. Buckler, L.S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | |
|-------------------------------|-------------------------------|---------------------------------|
| L-9 8" Tamarack, S42°W, 16.9' | K-9 2" Tamarack, N12°W, 91.5' | 7 Tag in Sign Post, N8°W, 38.5' |
| 8" Cedar, N2°E, 18.6' | 2" Tamarack, N20°E, 61.4' | 10" Aspen, N42°E, 50.9' |
| 6" Cedar, N71°E, 15.2' | 4" Spruce, N18°W, 97.6' | 10" Cedar, S66°E, 15.7' |
| 6" Cedar, N76°E, 6.3' | Sq. Post, S60°E, 1.0' | 3" Cedar, N75°W, 12.1' |

SIGNED BY

Gerald L. Wiggins
Gerald L. Wiggins

DATE 9-21-87

SURVEYOR'S MICHIGAN REGISTRATION NO.

23521

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

DATE

