LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co. Two Corners.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 44 N. ~~S.~~, R. 8 ~~E.~~ W.	I-10 H-10
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on 4-19 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19__, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
I-10 ¼ Cor. bet. Sec's. 26-27, set during original survey about 1840.
H-10 Center Corner, Section 27.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
I-10 Re-established corner midway and on line bet. two Sec. Corners.
Found no evidence of original corner or witnesses.

H-10 Corner placed at intersection of lines, connectting opposite Quarter Corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Placed 1" pipe with 4" aluminium cap at corner.
Squared and Scribed 7" Aspen at corner.
I-10 New Bearings: 5" Cedar, N9°E, 38.9' and 6" Soft Maple, N50°W, 43.6'

Placed 1¼" pipe, in SW. edge of wet marsh.
H-10 New Bearings: 12" Maple, S83°W, 51.6'

STATE OF MICHIGAN
BILLY D. BUCKLER
LAND SURVEYOR
NO. 8887
REGISTERED LAND SURVEYOR

SIGNED BY Billy D. Buckler DATE 2-4-74

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR DATE _____