

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Mackinac COUNTY
T 44N R 9W

DESCRIPTION OF CORNER 1/2 Cor. between Secs. 34-35

CORNER MONUMENT Iron fence post in N-S fence line

DATE MONUMENT PLACED AND WITNESSED 8-27-68

WITNESSES TO CORNER..... 6" Jack Pine (1/2 S NBT) S53°E 39.9°



8" Jack Pine (1/2 S NBT) N70°E 16.4°

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown surveyor. Found iron fence post and wood post.

Corner lies midway bet. Sec. Corners to north and south.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

3-17-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing