

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

B997893

For corners in

MACOMB

(County)

Located In:

Corner Code ##

CLINTON TWP.

1. Public Land Survey

T 2N R 13E

E-1

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

LIBER 06161 PC 243

Register of Deeds Stamp & File Number

I, BRUCE ANTCLIFF, in a field survey on NOVEMBER 23, 1993

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

GLO-Post, NO WITS. REMAIN

LCRC (1978) L2940, P350-PK NAIL

PK UTIL POLE, N'LY, 61.24'

PK UTIL POLE, S'LY, 58.55'

PK UTIL POLE, SW'LY, 158.80'

MDOT (1988)-PK NAIL

TOP CENTER FH, N15W, 51.28'

MDOT N&T IN PP, S12W, 58.28'

MDOT N&T IN 4" ELM, S50W, 89.52'

MDOT N&T SW COR WOOD FENCE, N44W, 90.36'

LCRC (1989) L4723, P608-PK NAIL

PK E SIDE UTIL POLE, N02E, 61.20'

PK NAIL W SIDE UTIL POLE, S03W, 58.54'

PK NW SIDE UTIL POLE, S70W, 158.81'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1" REBAR IN MON. BOX

FOUND AND VERIFIED TWO OF THE ABOVE WITNESSES.

VERIFIED MDOT DISTANCE TO E-13, T3N, R13E

93 DEC 22 AM 9:05

CARMELLA SABAUGH  
REGISTER OF DEEDS  
MACOMB COUNTY, MI

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

ACCEPTED BY THE MACOMB COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT 345  
OF 1990 AT A MEETING HELD ON  
12-1-93  
FRANK J. Dedecker, P.S., P.E., CHAIRMAN

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET MACOMB COUNTY REMONUMENTATION MARKER AND CAP #25826 IN EXIST. MON. BOX.  
WITNESSES

FND PK IN W FACE P POLE, NORTH, 58.68'

FND PK IN NW FACE P POLE, S29W, 63.59'

SET N&T - PK & MC TAG IN E FACE P POLE, S09E, 53.33'

SET N&T - PK & MC TAG IN NE FACE 24" POPLAR, S40E, 117.57'

SET N&T - PK & MC TAG IN SE FACE P POLE, N75E, 165.31'

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by

Bruce Antcliff

Date 12-9-93

Surveyor's Michigan License No. 25826

