SURVEY & REMONUMENTATION

APR 2 8 1995

■rveyor's Michigan License No.

28408

LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 C152279 or corners in 94 DEC 14 AM 10: 55 MACOMB Located In: Corner Code # CLINTON (County) Public Land Survey T 2N R 13E E-13 R LIBER 6527 PAGE 856 R T **Property Controlling** T R in Section S Т R Miscellaneous Т R Register of Deeds Stamp & File Number Property in Sec. R _ , Recorded Plat G H I J K L M Private Claims 3 4 10 -11---- 12 5 STEVEN E. DUNN MARCH 20, 19 , in a field survey on hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points - 18 16 15 - 14 - --13 nentioned in lines 1 and 2 above were in conformance with regulations and rules therefore required in the current manual of survey instructions of the United States Department of e Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the - 23 - .rner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the chigan Board of Land Surveyors or by a Decree of a Court of Law; established, 10 established, monumented, re-monumented, recovered, found as expressed below: 11 12 - 34 -- 35 - - -OTE: Not more than 4 corners, all in the same town and range, may be -31 13 recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: GLO POST - NO EVIDENCE OF ORIGINAL CORNER FOUND GLO ORIGINAL SURVEY L.C.R.C. E-1, T.1N., R.13E. E. NAME AND NUMBER WILLIAM E. SODERBERG, #17635 FOUND 1-1/4" PIPE IN MONUMENT BOX NAME AND NUMBER L. 3551 **OCTOBER 13, 1983** PLAT . 03 P. 161 HARMON FARMS JULY 26, 1919 SUPERVISOR'S PLAT NO. 2 L. 17 P. 030 JULY 21, 1936 Description of corner evidence found and/or method applied in restoring or reestablishing corner: E-13 SECTION CORNER COMMON TO E-1 ERIN/LAKE TOWNSHIP STEVEN E. DUNN PROFESSIONAL No. 28408 PROFESSIONAL No. 28408 Of the corner: FOUND 1/2" IRON ROD IN MONUMENT BOX IN CONCRETE PAVEMENT VERIFIED LOCATION BY COMPARING FOUND WITNESSES OF L.C.R.C. LISTED BELOW AND DISTANCE FROM E-13 TO D-13 AS SHOWN ON SUPERVISOR'S PLAT NO. 2 LISTED ABOVE AND ON MDOT RAW MAP, MACOMB COUNTY, SHEET 79. ALSO COMPARED DISTANCE FROM E-13 TO F-13 AS SHOWN ON PLAT HARMON FARMS LISTED ABOVE. FOUND WITNESS TIES POFESSIONAL COMMINISTRA L. 3551 P. 378 S.45°E. 123.63' NORTHWEST CORNER BRICK APARTMENT BUILDING N.40°E. 140.761 SOUTHWEST CORNER BRICK BUILDING FIELD MEASUREMENTS AND RECORDED DISTANCES E-13 TO D-13 2703.12' (M.) 2640.00' G.L.O. (R.) E-13 TO F-13 2699.14' (M.) 2640.00' G.L.O. (R.) E-13 TO E-12 2586.80' (M.) Description of monument for corner and accessories established to perpetuate locating the position of the corner E-13 T.2N., R.13E. I REPLACED 1/2" IRON ROD WITH A 3/4" x 24" IRON ROD WITH 2" DIAMETER ALUMINUM CAP STAMPED "MACOMB COUNTY MONUMENT MI ACT 346 #28408 IN AN EXISTING MONUMENT BOX. WITNESSES ACCEPTED BY THE MACOMB COUNTY SURVEY PEER S.48°W. GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN 67.49 LIGHT POLE PUBLIC ACT 345 OF 1990 AT A MEETING HELD N.43°W, 64.09 PK NAIL IN UTILITY POLE N.44°E. 140.74 SOUTHWEST CORNER OF BRICK BUILDING S.41°E. NORTHWEST CORNER OF BRICK APARTMENT BUILDING 123.45 S.33°F. 56.821 PK NAIL IN UTILITY POLE WILLIAM E. SODERBERG, P.S., CHAIRMAN ≡HE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER gned by Steven Nov. umm Date 9.1994