SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

C152294

| or corners in | 5 | ., | Dt |
|---|--|---|--|
| МАСОМВ | Located In: Corr | ner Code # | 94 DEC 14 AM 10: 56 |
| (County) | CHESTERFIELD | | 5.5 Sept. 1.110: 56 |
| . Public Land Survey | T <u>3N</u> R <u>14E</u> T R T R | K-6 | MACO SEDS |
| . Property Controlling in Section | S TR S | | LIBER 6527 PAGE 871 |
| Riscellaneous Property in Sec. | S TR S TR | | Register of Deeds Stamp & File Number |
| Lot No, Re | corded Plat | | A B C D E F G H I J K L |
| . I IIvate Claii iis | | | 2 6 5 4 3 2 3 3 4 7 8 9 10 11 12 |
| mentioned in lines 1 and 2 s required in the current ne interior, Bureau of Land orner points mentioned in lichigan Board of Land S | , in a field survey or requirements of P.A. 74, Michigan F above were in conformance with remanual of survey instructions of the at Management or by a decree of a lines 3, 4 and 5 above were in conformance or by a Decree of a Cod, re-monumented, recovered, found | P.A. of 1970, the corne egulations and rules to United States Depart Court of Law and for formance with the rule pourt of Law: establis | therefore that the es of the ished. |
| OTE: Not more than recorded on the | 4 corners, all in the same too his certificate. | wn and range, may | y be 12 31 32 33 34 36 36 35 |
| . Description of original m | nonument and accessories and/or subs | sequent restoration: | |
| GLO POST - NO EVIDE GLO ORIGINAL SURVI | ENCE OF ORIGINAL CORNER FOUND EY PERFORMED BY PRESTON 2-18-181 | 18 | * |
| <u>L.C.R.C.</u> L. 6000, P. 956 | NAME AND NUMBER MARTIN C. DUNN, #30081 | DESCRIPTION SET IRON ROD | <u>DATE</u> SEPTEMBER 7, 1993 |
| PLATS L35, P. 12 L 101 P. 1-6 NOT RECORDED | "ASSESSOR'S CRICKLEWOOD PLAT "BLAIRE MEADOWS NO. 1" "BLAIRE MEADOWS NO. 2" | F" JANUARY 12, 1956 SEPTEMBER 21, 1993 1994 | 23 |
| Description of corner ev | idence found and/or method applied in | n restoring or reestablish | |
| K-6 EAST 1/4 CORNER | | | |
| FOUND 1/2" IRON ROD VERIFIED LOCATION I | IN OPEN FIELD NORTH SIDE AT FOUR BY COMPARING FOUND WITNESS TIE | ND STONE 'S OF L.C.R.C. LISTED BI | BELOW. |
| N.6 WE | 5°E. 21.37' SET PK NAIL IN THE NOR 0°E. 11.31' SET PK NAIL IN THE SOU ST 4.86' SET PK NAIL IN THE NOR 0°W. 19.77' SET PK NAIL IN THE EAS: | UTH FACE OF 12" ASH RTH FACE OF 10" ASH | SELOW. STEVEN E. DUNN PROFESSIONAL SURVEYOR No. 28408 SURVEYOR OFESSIONAL OFESSIONAL OFESSIONAL SURVEYOR OFESSIONAL OFESSIONAL SURVEYOR OFESSIONAL OFESSIONAL OFESSIONAL OFESSIONAL OFFESSIONAL O |
| FIELD MEASUREMENT K-6 TO K-7 2640.0 | TS AND RECORDED DISTANCES 0' (M.) | | TOPESSIONAL SURFIN |
| Description of monument | for corner and accessories established | d to perpetuate locating | |
| K-6 T.3N., R.14E. | I REPLACED 1/2" IRON ROD WITH 3. STAMPED "MACOMB COUNTY MON | /4" x 24" IRON ROD WI IUMENT MI. ACT 345 # | ITH 2" DIAMETER ALUMINUM CAP #28408". |
| <u>WITNESSES</u> N.72°E. 21.37' S.60°E. 11.31' N.50°W. 4.86' | FOUND PK NAIL IN THE SOUTH FACE OF 12" ASH PUB ON | | ACCEPTED BY THE MACOMB COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT A MEETING HELD ON |
| N.50°W. 4.86' N.30°W. 19.77' | FOUND PK NAIL IN THE NORTH FACE FOUND PK NAIL IN THE EAST FACE OF | | WILLIAM E. SODERBERG, P.S., CHAIRMAN |
| THE SELECTED LOCA' EVIDENCE OF THE | TION IS ACCEPTED BY ME AND PROF ORIGINAL CORNER. | ESSIONAL SURVEYORS | S AS THE BEST AVAILABLE EVIDENCE OF THE |
| ned by Steven | E. Dunn | Date 22 | n. 9, 1994 |
| rveyor's Michigan Licer | nse No. 28408 | | |