

MAR 17 2000

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

SECTION

Macomb
(County)

Located In: Ray Twp. Corner Code #

1. Public Land Survey T -4-N R -13-E F -11
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

1091835
LIBER 9268 PAGE 23
12/27/1999 01:15:42 P.M.
MACOMB COUNTY, MI
CARMELLA SABAUGH, REG/DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, John N. Redash, in a field survey on January 13, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1993	1" iron bar	Survey	D. King	#30085	L 5969, P 136
1995	1" iron bar	LCRC	D. King	#30085	L 6586, P 208
1996	1" iron bar	Survey	D. King	#30085	L 7148, P 79
1998	1" iron bar	Survey	D. King	#30085	Unrecorded

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A mag nail with washer in centerline of asphalt pavement of west bound lane of 27 Mile Road currently occupies this corner. The following witness ties were used to verify its position. Two ties match current measurements from LCRC L 6586, P 208.

Field measurements were observed between the following corners:

E-11 to F-11	F-11 to G-11
2679.14 meas.	2667.64 meas.
2640.00 Rec. G.L.O. (40 Chains)	2640.00 Rec. G.L.O. (40 Chains)
2679.18 Rec. Survey L 5969, P 136	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the mag nail and washer with a 3/4" x 24" iron rod with a 2" diameter aluminum cap stamped "Macomb County Monument MI ACT 345 #37281" in a new monument box.

Witnesses are as follows:

Az 68°	34.18 feet	Found nail in SE face of 15" poplar
Az 128°	68.84 feet	Set mag nail with Macomb County Remon Tag in NE face of 10" maple
Az 178°	61.45 feet	Set mag nail with Macomb County Remon Tag in W face of utility pole
Az 270°	6.00 feet	Found P.K. nail in asphalt pavement from 1998 unrecorded King survey
Az 286°	75.40 feet	Set mag nail with Macomb County Remon Tag in W face of utility pole.

The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by John N. Redash
Surveyor's Michigan License No. 37281

Date 11/22/99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197
ACCEPTED BY THE MACOMB COUNTY SURVEY PEER
GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990 AT A MEETING HELD
ON 9/28/99
William E. Soderberg
WILLIAM E. SODERBERG, P.S., CHAIRMAN

REVISED MAY 14, 1971
REVISED JAN., 198
REVISED OCT., 199