

DEC 29 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER'S OFFICE
MANISTEE COUNTY

97-397 at 3:40 pm
OCT 24 1997

Deborah Dix
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For corners in MANISTEE (County) Located In: Corner Code #

Table with 3 columns: Survey Type, Location, Corner Code. Includes Public Land Survey, Property Controlling in Section, and Miscellaneous Property in Sec.

4. Lot No. Recorded Plat
5. Private Claims

I, Sammy S. Barnett, in a field survey on 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Grid table with columns A-M and rows 1-13. Contains numbers 6 through 36.

A. Description of original monument and accessories and/or subsequent restoration:

1837 GIO survey by John Brink 1958 survey by C. Dodd found iron pipe
1907 survey by J.H. Millard 1963 survey by R.A. Griffin # 13584
Undated survey by W. Swigrt, monument not given.
Undated survey by T. Vaillencourt, monument not given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On August 20th 1997 I found the 5" square monument set by R. A. Griffin, condition of witnesses are as follows,
# 1 Gone # 2 Found stump NW 26'+- # 3 Found stump SW 30'+- # 4 Found # 5 Found # 6 Found # 7 Gone # 8 Same as # 6, # 9 Found # 10 Same as # 5, # 11 Same as # 3, # 12 Same as # 4, # 13 Same as # 2, # 14 Found # 15 Gone # 16 Same as # 6 & # 17 Same as # 9, # 18 Same as # 5 & 10, # 19 Same as # 3 & 11, # 20 Same as # 4 & 12, # 21 Same as # 2 & 13, # 22 Same as # 14 # 23 Found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

On August 20th 1997 I accepted the found 5" square concrete monument as a careful and faithful perpetuation of the original corner, and took the following witnesses.

- 24 B. Oak 12" S56E 36.91' 40d spike in face (# 6 & 8 & 16)
25 W. Oak 6" S33E 40.25' dock spike in NE side (# 9 & 17)
26 B. Oak 12" Due South 39.07' 40d spike in face (# 5 & 10 & 18)
27 B. Oak 12 N65W 14.90' 40d spike in face (# 4 & 12 & 20)
28 3/4" pipe S21W 190.66' GPS point by Caldwell

Corner M-04 ratified by the Manistee County Peer Group according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument Act, MCL 54.261 et seq.). Date of Peer Review: OCT 7 1997

Signed by Sammy S. Barnett
Surveyor's Michigan License No. P S # 16923

