

1993

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in
Manistee _____
(County)

Located In:

Corner Code #

	21N	13W	I-12	K-10
1. Public Land Survey	T _____	R _____		
	T _____	R _____		
	T _____	R _____		
	T _____	R _____		
2. Property Controlling in Section	S _____	T _____	R _____	
	S _____	T _____	R _____	
3. Miscellaneous Property in Sec.	S _____	T _____	R _____	
	S _____	T _____	R _____	

REGISTER'S OFFICE
MANISTEE COUNTY

93-303 AT 11:45 A.M.

MAY 12 1993

Penny A. Repen
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Norman C. Caldwell, in a field survey on September, 1992, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-12	Post Placed by John Brink, 1839 N37½°E 84 lks. (55.44') 11" Y. Pine	K-10	Post Placed by John Brink, 1839 S8°W 48 lks. (31.68') P. Pine N8°E 59 lks. (38.94') P. Pine
------	--	------	---

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-12	<u>1/4 cor., Sec. 34 & 35, T21N-R13W</u> Survey by Fargo Eng. Co. on July & Aug. 1909 Fnd. a 1/4 post - Not U.S., Not used - No pipe set Manistee County Surveyors record pg. 16 J.H. _____, Fargo Eng. Co. July & Aug. 1907 S75°E 70 lks. 9" B. Oak S68°E 84 lks. B. Oak Consumer Powers Property Survey by Paquette Surveys R.L.S. #16938 dated 7/74 - 4/79. Did not find cor. Calculated a position for cor. at a pnt. equal dist. on a straight line between sec. cor. - did not set anything. U.S. Forest Service land cor. record card Robert Griffin searched for cor. in 1963 & fnd. nothing. Presumed this to be a lost corner.	K-10	<u>1/4 cor., Sec. 25 & 26, T21N-R13W</u> Survey by Fargo Eng. Co. in July & August 1909 No U.S. Evidence - Not Used No Pipe Set
------	---	------	--

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12	<u>1/4 cor., Sec. 34 & 35, T21N-R13W</u> <u>At midpt. on line</u> Placed 2" D. Iron Pipe w/brass cap and is accepted as a careful and faithful reestablishment of the position of the original corner. N20°W 26.72' 8" W. Oak N50°E 7.40' 10" W. Oak Due South 39.44' 6" W. Oak S81°W 37.73' 10" W. Oak N80°E 58.14' 3/4" Pipe #12018 South 1.0' Carsonite Witness Post	K-10	<u>1/4 cor., Sec. 25 & 26, T21N-R13W</u> <u>At midpt. on line</u> Placed 2" D. Iron Pipe w/brass cap and is accepted as a careful and faithful reestablishment of the position of the original corner. N20°W 55.60' 8" W. Pine S85°W 30.56' 6" W. Oak S16°W 62.29' 24" W. Oak S31°E 39.96' 6" W. Oak N56°E 54.85' 3/4" Pipe #12018 South 1.0' Carsonite Witness Post
------	---	------	--

Signed by

Norman C. Caldwell

Date

12 JAN 93

Surveyor's Michigan License No.

12018

Corner K-10 established by the Manistee County Peer Group pursuant to P.A. 123 of 1915 as amended by P.A. 345 of 1990, as amended. Date of this survey APRIL 25, 1993

