

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--

LOCATED IN--

CORNER CODE NUMBER

1. PUBLIC LAND SURVEY_____ T. _____ 21N N. 14W E. S., R. W.

G9 (MC West Side Lake)

2. PROPERTY CONTROLL-
ING IN SECTION_____ ,T. _____ N. S., R. E. W.

#003

3. MISCELLANEOUS
PROPERTY IN SECTION_____ ,T. _____ N. S., R. E. W.

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER'S OFFICE
MANISTEE COUNTY

#93-316 AT 11:56

APR 20 1993

Penny A. Leemon
REGISTER OF DEEDS

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Patrick R. Leemon do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on January 23 1993 established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Meander Corner common to Sec's. 21 and 28 of T21N R14W

1962 Survey by Robert A. Griffin

Monu. Set 6" round by 60" long concrete monu. with 3" brass disk.

Witnesses

W.Pine 7 N43W 43.10'

R.Maple 7 S66W 41.20'

Cedar Post 4 East 1.5'

6"x60" conc. monu. marked 1/64 is west 247.30'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I found the monument and all the witnesses except the maple which was cut down, to be in good condition. The monument extends 1' above the surface. Liber 73 Page 59 documents the history of this corner as perpetuated by Griffin.

C. Description of monument for corner and accessories established to perpetuate locating the position of corner:

Meander Corner common to Sec's. 21 and 28 of T21N R14W

Monu. 6" round by 60" long concrete monu. with 3" brass disk.

Witnesses

W.Pine 16 N43W 43.02'

R.Maple 5 S61W 39.22'

Cedar Post 4 East 1.5'

6"x60" conc. monu. marked 1/64 is west 247.30'

R.Oak 5 S24W 24.90'

Tw.R.Oak 14x6 N14W 23.08'

W.Edge of Pine Lake is East 12'

SIGNED BY

Patrick R. Leemon

DATE

January 25, 1993

SURVEYOR'S MICHIGAN REGISTRATION NO.

31595

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. MLM735
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 197
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS

Corner 6 - 9 (no west) ratified by the Manistee
County Peer Group pursuant to P.A. 123 of
1945, as amended by P.A. 345 of 1990, as
amended. Date of Peer Review: FEB 1 1993

REC 12000

SECTION

