MIDLAND COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

		, 1.1.61.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.
Midland	Located In Corner Code #	
(County)		
1. Public Land Survey	T 15N R 1W E13	
Property Controlling in Section	S T R	
Miscellaneous Property in Section	S	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	
5. Private Claims:		A B C D E F G H I J K L M
requirements of PA 74, Mi and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	field survey on Oct. 12, 2011 do hereby state that under chigan PA of 1970, the corner points mentioned in lines formance with regulations and rules therefore as required in vey instructions of the United States Department of the anagement or by a decree of a Court of Law and/or that the lines 3, 4 and 5 above were in conformance with the rules of Land Surveyors or by a Decree of a Court of Law, monumented, recovered, found as expressed below:	1
NOTE: Not more than be recorded on this ce	2 corners, all in the same town and range, may rtificate.	9 10 30 29 28 27 26 25 11 12 31 32 33 34 16 36
		13
A. Description of original monument and accessories and/or subsequent restoration:		
2) Spruce 8' - 1852 – GLO 2) Correct S 3) Spruce 8' 4) Tamarack - 1899 – CSR Tamarack S bearings 1914 – CSR	k 11" N88°E 31 L. " N2°W 22 L.) – Sub – T14N, R1W – A. Burt	 - 1985 – LCRC #609 – D. F. Ledy – Set 1 ¼" pipe – 4' long Corner location determined by prolongation of the N ½ of the east section line of Sec. 32 & a prorated distance from CSR notes. Location agrees with occupation fence on the east line. 5) N45°W 25.95' nail in 8" Maple; 6) N25°E 28.05' nail in 12" Oak; 7) S25°E 16.40' nail 10" Tw. Maple
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:		
E13 & E1 – Standard corner common to Sections 32 & 33, T15N, R1E & Section 4 & 5, T14N, R1W – Excavated large area in swamp and find 2 ½" dia. X 16" long wood post bottom with axed point. No GLO evidence. Fits Gibb's survey dimensions N, S, E & W closely. Wood stake accepted as a careful and faithful perpetuation of the position of the original corner.		
- <u>Reference F</u> survey.	Pt. – N67°36'W 9.03' from "E13 & E1" found 1 1/4" iroi	n pipe per Ledy. 1 1/4" pipe not utilized as "E13-E1" in this
C. Description of monun	nent for corner and accessories established to perpe	etuate locating the position of the corner:
E13 & E1 - Replaced 2 Set Blue Ca N10°E 28.66 N22°W 34.3 N88°E 27.74 S44°W 15.9	1/2" x 16" point wood post bottom with stamped 4" DN rsonite Post 1' SW 6' to set nail & tag (N & T) at fd. Nail in W. side 12" C 4' to set N & T in NE side 11" Oak scribed 'XBT' 4' to set N & T in N. side 6" Red Maple 1' to set N & T in SE side 4" Oak .03' to Reference Point 1 1/4" iron pipe	NR Aluminum Cap on 1" x 5' long galv. iron pipe.
Signed by: Surveyor's Michigan	A TOTAL TOTA	ate: 10/15/2017 39068
ourveyor a micrigan .	TOE119E 140 39000	