

SURVEY & REMONUMENTATION

APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

APR 28 1995

COMMISSION

151

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

For corners in

MIDLAND
(County)

Located In:

Corner Code #

7 DEC 94 8:23 A.M.

BEVERLY J THAYER
REGISTER OF DEEDS

1. Public Land Survey T 15N R 1E E-1
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, PAUL B. LAPHAM, in a field survey on NOVEMBER, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1831 HARVEY PARKE
WIT.-HEMLOCK 12" S60°E 34 LKS.
HEMLOCK 7" N28°E 26 LKS.

NO C.S.R.

8-21-67 M.S.H.D. RIGHT-OF-WAY MAPS

6-17-80 JERRY JONES
FOUND BRASS DISC. ON 1" PIPE 8" DEEP

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1"x8" PIPE ABOVE MICH. STATE CAP ON 3' LONG PIPE IN MON. BOX 18.95' WEST OF C OF PVM'T. (M.S.H.D. 18.28').
EXCAVATED TO 3' DEPTH.
FOUND NO OTHER EVIDENCE.

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument.

Corner, E-1 was approved for remonumentation at a Peer Review Committee Meeting on 11-28, 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1: N.W. Cor. Sec. 4
Set 5/8" x 18" re-rod with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box.

WITNESSES:
EAST 18.95' C M-30 PVM'T
N45°W 83.10' TELE. RISER BOX
S80°W 52.90' - PK N&T IN 5' DIA. CULV.
EAST 96.0' - N&T IN POWER POLE



Signed by

Paul B. Lapham

Date

12-01-94

Surveyor's Michigan License No.

9433