REMON. COR. G-11, MILLS TWP.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For con									
Milytariu	(County)	Located in:	Comer Code #	505					
1. Publ	lic Land Survey	G-11 GURVEY &	STATE OF MICHIGAN MIDLAND COUNTY REMONUMENTATION & FILED						
in S 3. Misc	perty Controlling ection cellaneous perty in Sec.	ST_R	EB 2 3 2001	Register	12 of Deeds S	/28/200	0 8:44 FiighNy(:27 AN	
4. Lot	No, Recorded Pl	at	SECTION		C D	e f G		1 .1	K L
I, RODNEY CLAYPOOL, in a field survey on July 25, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules			2 - 6 3 + 7 5 + 1	5 -	4 -	- 3 -	11	1 12 + 13	
of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:				6 - 18 7 1 8 - 19		16	- 15 · - 1	14	24
NOTE:	: Not more than 2 comens recorded on this certific	s, all in the same town ate.	and range, may be	9 + 30 10 - 30 11 - 31	29-	28 -	27	26 + 35	- 25 - 36
A. Des	cription of original monumer	it and accessories and/o	r subsequent restoration:	13		<u></u>		1	
G-11	Corner common to Section	ns 27, 28, 33 and 34							
	Survey by Glo, 1830's, set Survey by M. Hunter, 1960 Survey by D. Whittier, 3/2"	5, 1968, used	e road				900	MIEY D	
B. Des	scription of corner evidence t	ound and/or method app	olied in restoring or reesta	blishing corn	er:		CLA)	YPOO! And	·) ;
G-11	Corner common to Section	ns 27, 28, 33 and 34				j.		VEYO# Na. 9341	الخار
	Found 3/4" pipe, pinched e	nd down 2' deep per sun	veys by M. Hunter and D.	Whittier.	· . ·.			n n	The state of the s
			abliabad ta namatusta la	acting the po	ition of th	an norma	\r		

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
- Corner common to Sections 27, 28, 33 and 34

Set ¾" pipe and brass cap stamped Midland Co. Remon Cor PS 29241 in monument box and is accepted as the best available evidence of the position of the accepted corner.

N 45 Deg W, 90.11, nail and plastic disc in power pole S 10 Deg W, 27.54, centerline telephone box S 15 Deg E, 32.67, centerline gate post North, 8.6', centerline payement

Surveyor's Michigan License No. 29241

Date 12-12-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971
Revised Jan., 1983

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY