FEB 1 3 1998

SECTION		ment of Act 74, Mich. P./	
For corners in	riilig Kequile	ment of Act 74, when. F.	S₩ C - n
Raisinville	Located In:	Corner Code #	TYPE TO THE
(County)			SERVE SECOND
1. Public Land Survey	Raisinville TR TR TR		OR RECORD PH 3: 50 OF DEBOS DENTY, MICH
 Property Controlling in Section Miscellaneous Property in Sec. 	STR ST_6S_R_8E ST_R	2	Register of Deeds Stamp & File Number
4. Lot No. 53 (NE corner)	Recorded Plat Supervisors	Plat No.1 L 8 of Plats 1thru	15 A B C D E F G H I J K L
5. Private Claims			2 6 5 4 3 12 12 12 12 12 12 12 12 12 12 12 12 12
hereby state that under requirem lines 1 and 2 above were in con- manual of survey instructions of the or by decree of a Court of Law ar conformance with the rules of the	, in a field survey on, in a field survey on, ents of P.A. 74, Michigan P.A. of formance with regulations and rule he United States Department of the nd / or that the corner points mentice Michigan Board of Land Surveyomented, recovered, found as express	1970, the corner points mentions therefore as required in the contraction. Bureau of Land Managoned in lines 3, 4 and 5 above were or by a Decree of a Court of	7 do 5 ned in 6 ns 17 16 ns 17
NOTE: Not more than 2 corne on this certificate.	ers, all in the same town and rang	e, may be recorded	11
Monroe County Road Commiss	ion Corner		12 31 32 33 434 33 34
Intersection of Raisinville Road ar	nd Stewart Road to the West.		13
1934 O.A. Case Set 1"x3 1949 Angelo Marino Iror 1960 Angelo Marino four 1981 Angelo Marino four SW, 70.20' nail in N 1988 G.B. Warnke found nail/washer in the N60°E, 28.20' to a	N face P Pole; NW, 92.17' nail I !/2 " Iron pipe at surface; W , 7	nail in NW face P Pole; SE, in NE face P Pole. 70.10' to a nail/washer in N f. 48,90' to a chiseled "A" in to	rs plat #1 of Raisinville Twp. 41.60' to a nail in NE face P Pole; ace Elec. Pole; S20° E, 41.35' to a fnd op W end of a 36 " conc. culvert;
10/23/97 found 3/4 " x 8"	ence found and/or method appli lron pipe at surface. Excavated pieces of clay tile 1' +/- to north, ot appear to be significant. Set	d a 1.5' x 1.5' found bent axlo	e 1" x 30" long, 3/4" iron located above straight I under the axle remon cap at location of axle.
RATIFIED BY PEER G	ROUP, P.A. 345 OF 1990, M	ONROE COUNTY, MICHIG	AN DATE: DE COUNTY REP. 12/9
Set 1"X36" iron pipe with witnesses: West; 72.1 S 40° W; 88. S 50° E; 41.5		t box. C.R.C. tag in the NE face uti of a fire hydrant . .C.R.C. tag in NE face of pov	
Signed bySurveyor's Michigan License	. a. Wanke No. 41913	Date	PROFESSIONAL SURVEYOR No. 41913 PROFESSIONAL SURVEYOR No. 41913