

MAR 0 9 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MUSKEGON RECEIVED FOR RECORD

1998 DEC 23 AM 8: 12

Parrie Carter

SECTION For corners in Located In: Corner Code # MUSKEGON (County) T 9N_ R <u>14W</u> 1. Public Land Survey Т URER 2187 PAGE 907 T T 2. Property Controlling T In Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. , Recorded Plat 5. Private Claims in a field survey on July 7 I, Stephen V. Vallier do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: G.L.O. set post. 1-4 1837 22° 22.44' 24" Hemlock 20° 2.64' 18" Hemlock Muskegon County Survey Records page 12, iron bolt in C/L of railroad. 1940 Era 96.30 Spike in Pole NE SW 56.00 Spike in Pole Spike in Pole NW 42.80' **See Section A, Page 2** Description of corner evidence found and/or method applied in restoring or reestablishing corner: I-4 Found capped rod in the center line of old railroad track, now bike path, South of center line. Set 2¾" x 30" cast-iron county survey monument. Set Mag Nail C/L Bike Path N 22° E C/L Fire Hydrant South 30.75" 125.26' 103.40 N 12° W Power & Light Pole Found Nail East Side S 24° W Found Nail Northwest Side Power & Light Pole 56.16 1.44' S 16° E Telephone Pole Found Nail East Side N 30° E 54.83' C/L Catch Basin Accepted position of corner due to historical usage and documentation. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


N 22° E 125.26 Feet C/L Fire Hydrant N 12° W Found Nail East Side 103.40 Feet Power/ Light STEP. IEN S 24° W Found Nail 56.16 Feet Power/Light Northwest Side VALLIER \$ 16° E Found Nail 91.44 Feet Telephone Pole East Side Land N 30° E 54.83 Feet Surveyor No. South 30.75' set mag nail at C/L of bike path. 28428 Surveyor's Michigan License No. _ FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 2

I-4 Set 21/2" X 30" cast-iron county survey monument.

REVISED MAY 14.19 REVISED JAN., 19 REVISED OCT., 19

Section "A"

1950 Era	M.C.R.C. NE NW Sw	Tie Book, 47.44' 103.40' 56.20'		
1979	Corner re NW NE SW	ecorded by 103.40' 47.44' 56.20'	Francis Smith in Liber 11 Spike in power pole Center of street sig Spike in power pole	gn
1992		24" cappe W W E		S6, page 740. Found P.K. Nail in center line of Railroad. Spike in Power Pole Spike in Power Pole C/L of Catch Basin Spike in Telephone Pole



Int When 22,1998

SUPERFY A RELYCY OF GRUNNINGN

WAR 0 9 199**9**

SECTION

;;