SURVEY & REMONUMENTATION

HAFP 2052 PAGE 573

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIVED FOIL RECORD

MAR 0 6 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1797 EEC 30 PM 3: 119

Pairie Carter RECEPTER OF REEDS

For corners in SECTION	Fining Requirement of Act 14, Mich. F					
Muskegon (County)	Located In:	Corner Code ##				
1. Public Land Survey	T <u>10N</u> R <u>17W</u> T R T R	J_13				

2. Property Controlling In Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec.

4. Lot No		, Recorded	Plat	 			`-	
5. Private Cl	laims	- 	~~~~·	 · 				_
	-				•	•	٠.	

Ralph W VanRiper, in a field survey on Oct. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded. on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Quarter Corner between Sections 35, T10N R17W and 2, T9N R17W

Post set by GLO Surveyors in 1837: W Oak 8" N34°W 35L and Pine 11" N69°E 34L

MCRC 1950's Witness Map: NE 47.4' SW Cor. Brick Post; NE 56.03' Face of Fire Hydrant SE 45.17' P.P.; NW 51.26' City B.M.

Current Witness Book: SAME WITNESSES AS 1950's WITNESS MAP

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found PK Nail over 3/4" Pipe Accepted corner based on Historical usage and documentation

10

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKECON COUNTY PEER GROUP IN ACCURDANCE WITH P.A. 945, OF 1000

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2 3/4" Cast Iron Monument with County Survey Cap

56.49' Center of Top Bolt of Fire Hydrant N 34° E 43.19 Set PK Nail in SE Side of Power Pole 44° E 44.991 Set PK Nail in SW Side of Power Pole 17° 97.54 Set PK Nail in W side of Guy Pole W S 40° W 44.47

N 39° W 51,42

Set PK Nail in SE Side of Utility Pole Found Center of City Bench Mark Cap in Concrete



Signed by Mafe W. Un	12:
Surveyor's Michigan License No.	16946

Dec. 26, 1997 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983