STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Marquette	COUNTY
	τ	<u>43 N</u>	R 24 W
DESCRIPTION OF CORNER	1/4 corner for sections 31		
CORNER MONUMENT	1" iron pipe with 4" aluminum o	сар	
DATE MONUMENT PLACED AND W	VITNESSED 9/12/69, F. J. Bray		
WITNESSES TO CORNER	7" Cedar (1/4 S) (NBT) N 15° E	, 16½ links	
N 3 h	8" Cedar (1/4 S) (NBT) S 52° E	, 22 links	
	AND		
CIRCLE CORNER REGISTERE	D		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line and the single proportioned measurement between section corners to east and to west. Blazed and signature trees near. No original evidence found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Z

REGISTERED LAND SURVEYOR

DATE 10/3/69

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68