MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_43 NR_25 W.

			Marquette COUNTY
DESCRIPTION	OF	CORNER	1/4 corner between sections 3 and 4
DESCRIPTION	OF	CORNER	MONUMENT_1" pipe with 4" Brass cap
WITTNESSES	то	CORNER	12" Elm - N 19 W - 22 Links
			8 H. Maple - N 62 W - 16 Links
			9" S. Waple - S 47 W - 21 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

All possible B.T.'s badly rotted. Established by proportionate measurement.

Corner placed and witnessed October 11, 1950.

SURVEYOR'S SEAL

NOV 9 1950
FORESTRY DIV.
CONSERVATION DEPT.

SIGNED SEAR C Sed Situ DATE 11/7/50
REGISTERED LAND SURVEYOR