## STATE OF MICHIGAN DEPARTMENT 0F NATURAL RESOURCES

## LAND CORNER RECORD

	<u>Marquette</u> COUNTY
	T <u>44 N</u> R <u>23 W</u>
	<u>30</u>
DESCRIPTION OF CORNER	West $1/16$ between sections $\frac{30}{31}$
	l" iron pipe with 4" aluminum cap
DATE MONUMENT PLACED AND WITNESSED 5/16/69, F. J. Bray	
WITNESSES TO CORNER	9" Balsam (W 1/16) (BT) S 46° W, 39% links
N 3 1	5" Tamarack (W 1/16) (BT) N 22° W, 68 links
	AND
CIRCLE CORNER REGISTERED	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line and the single proportioned measurement between section corner to west and 1/4 corner to east.

SURVEYOR'S SEAL

**DISTRIBUTION:** 

REGISTERED LAND SURVEYOR Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing