

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 & 44 N.R. 24 W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 36, 1

CORNER MONUMENT 1" Iron pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 8-25-61

WITNESSES TO CORNER..... 6" Cedar (1/4S) (NBT) S 60° W 10 links



10" Hemlock (1/4S)(NBT) East 30 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from cedar 9" N 35° E, 47 links. B.T. (stump with faces) and Hemlock 14" N 60° W, 14 links (badly decayed but in proper bearing & distance.)

Corner found by Forester Metsa.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler. DATE April 27, 1964
REGISTERED LAND SURVEYOR
Billy D. Buckler