

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 N. R. 23 W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 27 and 28

CORNER MONUMENT One-inch iron pipe with 4-inch aluminum cap

DATE MONUMENT PLACED AND WITNESSED April 16, 1962 by A. Metsa and W. Oliver

WITNESSES TO CORNER..... Elm 14 N 7 W 21.0 links



Cedar 11 S 40 W 49.0 links

Cedar 12 S 87 E 27.5 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

The corner was set from original cedar B.T. The tree was fallen against a birch, the heart of the tree was completely rotted, but tree was still live. The face was in poor condition, the scribe marks having completely disappeared. Tree had innumerable cruiser's names registered on it dating back to 1916. One cruiser had marked it as a B.T., others had marked it for the 1/4 corner between 27 and 28. Line was blazed north and south from this point. Corner checks in chainage to swamp edges to south and to north.

SURVEYOR'S SEAL

SIGNED

Aune G. Metsa

REGISTERED LAND SURVEYOR

DATE

4/16/62