

Marquette County

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. 45N N. 24W E. S., R. W.	G-10, H-11
2. PROPERTY CONTROLLING IN SECTION_____	T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on October 21, 1983, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

G-10 - East 1/4 Cor. of Section 28; Wood Post - Tamarac 14" - N60°W - 19 Lks.; Tamarac 10" - N45°E - 25 Lks.

H-11 - North 1/4 Section Cor. of Section 34; Wood Post - Spruce 7" - N30°W - 21 Lks; Spruce 6" - S45°E - 18 Lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

G-10 - Set M.P.O.L. between the N.E. & S.E. Sec. Cors. of Sec. 28. No sign of O.B.T.s

H-11 - Set M.P.O.L. between the N.E. and N.W. Sec. Cors. of Sec. 34. No sign of O.B.T.S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-10 - 1" pipe, 4" aluminum cap; 8" Tamarack - S35°W - 30.6'; 5" Cedar - N81°E - 16.6'; 4" Cedar - N32°E - 21.6'; 3" Balsam Fir - N60°W - 4.8'.

H-11 - 1" pipe, 4" aluminum cap; 4" B. Spruce - S42°E - 15.1'; 3" B. Spruce - S40°W - 9.0'; 4" B. Spruce - N70°W - 11.6'; 7" Cedar - N12°W - 23.9'.

SIGNED BY David B. Babbitt DATE 10-24-83

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

PLACE SKETCH ON BACK OR ATTACHED SHEET