LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-	:	CORNER CODE NUMBER
1, PUBLIC LAND SURVEY	т. <u>45</u> жх, і	R. 26 W.	A-1
2. PROPERTY CONTROLL- ING IN SECTION——	,T N. S., 1	R E.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T N., S., I	E	
4. LOT NO, RECORDED PLAT			
5. PRIVATE CLAIMS			

REGISTER OF DEEDS STAMP AND FILING NUMBER

A. Description of original monument and accessories and/or subsequent restoration:

Mich. Dept. of Conservation NW Sec. cor. of Sec. 6 (Twp. cor.) Set 1" pipe with 4" brass cap 4-12-65 N.B.T.s 10" jack pine - $N62^{O}W$ - $98\frac{1}{2}$ Lks 12" red oak - N $9^{O}E$ - 98' Lks

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Found both Conservation Dept. N.B.T.s from 1965 record but no monument found. Set new monument from found N.B.T.s and marked two additional N.B.T.s.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D.N.R. monument
Old N.B.T.

12" jack pine - N62°W - 65.0'
Old N.B.T.

20" red oak - N 9°E - 65.0'
5" maple - S30°W - 16.6'
5" maple - N89°E - 49.3'

SIGNED BY THE Land B. Bestit

DATE 9-12-84