

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 6 T 45N R 30W	12
	S T R	(GCDB 140620)
	S 6 T 45N R 30W	13
	S T R	(GCDB 160620)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	5			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 12 05/09/16
13 05/10/16 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,
monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 6) Center-South 1/16 corner, Section 6. Not previously monumented.

(13-Sec. 6) Southeast 1/16 corner, Section 6. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 6) Established the position for the corner midway and on a straight line between Quarter
corner 1320.75' south and Center of Section 6 1320.75' north.

(13-Sec. 6) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners, those to the north, west, and east being monumented.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Sugar N03°E 17.9' mrkd "1/16S BT"
8" Maple N88°E 43.95' do
5" Poplar S29°W 8.65' do
7" Poplar N64°W 16.7' do
Set sq'd cedar post adjacent.
E= 7914756.97 N= 171634.49

(13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Balsam N03°W 30.9' mrkd "1/16S BT"
4" Poplar N82°E 32.7' do
5" Balsam S78°W 25.75' do
6" Balsam N39°W 42.15' do
Set sq'd cedar post adjacent.
E= 7915153.07 N= 171639.99

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum
Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/19/2016

For the Michigan Department of Natural Resources, Forest Resources Division

