SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

For corners in		_			maa f	te o	.	11. O.	, Č
MARQUETTE (County)	_ Located In:	Corner (Code #		7777 (EG Z	2 AM	II : Z	Þ
1. Public Land Survey	T <u>46N</u> R <u>25W</u> T R	K-1			Patri	ecie 4 STER 1	L. MA	ntee	A.
	TR TR				4(f. Qf	oten (א טבב	ns V	1 ,
2. Property Controlling in Section	S TR S T R							_	
3. Miscellaneous S Property in Sec. S	S T R S T R						\mathbf{R}^2	•	
4. Lot No, Reco	rded Plat			Reg	ister of D	Deeds S	Stamp &	k File	Numb
5. Private Claims				* 5	a b		C 11	- T	<i>v</i> 1
				1 A B	1 1	E F	H t		+ 1
				2 - 6		 4 -	- 3-	 2 -	j
I, GERALD W. CARLSON	. in a field survey on Oct	ober	. 19 99 .	3		+	+	++	+
do hereby state that under requi	rements of P.A. 74, Michigan	P.A. of 1970,	the corner points	4 7		 9	10-	<u> </u>	1
mentioned in lines 1 and 2 abov		-		5		1		1-	
required in the current manual of s				6 18	17-	16-	15-	14	1
Bureau of Land Management or mentioned in lines 3, 4 and 5 abo				1				 	
Land Surveyors or by a Decree				!!	20_	21_		23	
recovered, found as expressed bele		,	, ,,						
				9					
	ers, all in the same town and	I range, may b	e recorded	10 30	29	 28	27-	26	_ _2
on this certificate.				11				+	
A. Description of original mor	nument and accessories and/o	or subsequent	restoration:	12-31	32	-33-	34-	35	3
K-1: Carner common to Section				1.3	TIFIED	BV DE	FER OF		نسلب
1845: William Ives original sub	division survey notes describ	e the corner m			A. 345 C			i O O F	
wood post 14 links East of con			441	-	Lan		13,	بعيليين	n l
6" Yellow Birch S35W,	21L 5" Yellow	Birch S3:	2E, 11L			1 / 3 /	1,10	29	
1976: A Land Corner Recordat	ion Certificate recorded by D	avid B. Babbitt	, .P.S. #21558,	Ų	11E		farla faril	-/	
in Liber 1 RC, Page 155, indicates east of the corner for Sections	ites he set a one inch pipe wi 35 and 36, T47N-R25W. Di	ith a four inch id not recover	aluminum cappe any GLO eviden	ed monume					
7" Sugar Maple S38E,	21.40' 7" Sugar I	Maple S6	6W, 48.00'						
DNR monument West,	9.24'								
1976: A Section Breakdown M Sections 35 and 36, T47N-R25				cated 9.24	' East of	a stan	dard co	rner f	or
B. Description of comer evide K-1: 1999: No original corner of ground. Old barbed wire fence Distance West is 2662.41', Ea	evidence found. Found and a runs East from here.					cap pr	ojecting) O.4°	abov
C. Description of monument if K-1: 1999: Stamped the acce	epted 4 inch aluminum cappe							groun	ıd witi
MCR 1999 and established nev 8" Sugar Maple \$32E,	w references: 21.75' (Babbitt NBT)	7"	Sugar Maple	\$73W,	48.15	(Bahhi	itt NBT)	
	34.02'	9"	Red Maple	N25E,	12.43'			r	
Green Steel Sign Post w/ Yello	w Survey Marker Sign	S10W, 1.15	5 '						
Note: Bearing trees have painted Bk. 14. Pg. 141	ed face, butt, and side nail bl	azes, d.h. mea	suring nails, and	l stamped	B.T. Tag	s affixe	ed.		

GERALD W. CARLSON SURVEYOR No. 24589 POFESSION

of HICH

Surveyor's Michigan License No.___

24589

12-8-99 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT.. 1995