

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Marquette COUNTY
T 46 N R 26 W

DESCRIPTION OF CORNER Section corner for sections $\frac{6}{5}$ $\frac{7}{8}$

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10/20/70

WITNESSES TO CORNER..... 6" W. Pine (S. 6) (MBT) N 65° W, 15.0'



12" W. Pine (NBT) N 10° E, 22.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set from stumps of original witness trees. $\frac{1}{2}$ " iron rod in place. This is a corner on record at Marquette County Road Commission. CCI location poster on 12" Maple west side of road, $7\frac{1}{2}$ chains east to corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE 11-23-70

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68