

1994 DEC 28 PM 5:56

JOB NUMBER: 94030  
SHEET NO. : 1-491

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MARQUETTE  
(County)

Located in:

Corner Code #

*Patricia L. Hanley*  
REGISTER OF DEEDS

- 1. Public Land Survey      T 47N R 27W      E/F-13  
                                   T 46N R 27W      E/F-1 ✓  
                                   T        R         
                                   T        R
- 2. Property Controlling    S        T        R         
    in Section               S        T        R         
                                   S        T        R
- 3. Miscellaneous           S        T        R         
    Property in Sec.        S        T        R

#2

LIBER 1 PAGE 161  
Register of Deeds Stamp & File Number

- 4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- 5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	16	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, GERALD W. CARLSON, in a field survey on Tuesday, December 20, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E/F-13: Meander Corner on the South line of Section 33, T47N-R27W on the East shore of Long Lake.  
1846: Austin Burt's original notes describe the corner monument as a 6" Cedar meander corner referenced by:  
7" Spruce S69 1/2E 11 1

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Corner position established on line from the found South 1/4 Corner of Section 33 and the found M.C. on the West shore of Long Lake at the GLO distance 2191.20' (33.20 chains) West of the South 1/4 Corner of Section 33.

RATIFIED BY PEER GROUP  
P.A. 345 OF 1890  
*Luigi J. Bussone*  
DATE Dec 6, 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Set a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:  
21" Red Pine N86W 18.78 ft.  
6" Maple N60E 5.62 ft.  
7" Spruce S30E 14.71 ft.  
12" Red Pine S08W 6.85 ft.  
Steel sign post N08E 0.93 ft.  
Monument is 0.3' above ground and 114.0' East of the waters edge.  
Bk. 5, Pg. 125



Signed by Gerald W. Carlson  
Surveyor's Michigan License No. 24589

Date 12-22-94