SURVEY & REMONUMENTATION

MARQUELIE COUNTY MICHIGAN RECEIVED FOR RECEPT

JOB NUMBER: 94030

SHEET NO. : 1-489

APR 2 8 1995

_____, Recorded Plat _

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 1994 DEC 28 PN 5:56

For corners in

Property in Sec.

5. Private Claims __

4. Lot No. _

2.

MARQUETTE COI	MMISSION Ocated In:	Corner Code ##
(County)		
Public Land Survey	T 47N R 27W	D/E-13
	T R	
	T R	12
	T R	(TB)
Property Controlling	S T R	
in Section	S T R	
Miscellaneous	STR	

S T R

LIBER Register of Deeds Stamp & File Number

I, GERALD W. CARLSON , in a field survey on Tuesday, December 20 , 19 94 ,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	·					
2	6	5	_4_	3	2_	_
3		\Box				
4	_ 7	_	9	 10	11	12
5						
6	 18		16	15	14	 13
7						
8	 19	20	21	22	23	
9	L Î					
10	30	29	 28		—26 —	 25
11		ĽĽ	_Ĭ_		Ĭ	_ <u>_</u>
12	31	-32	33	34—	35	36
	l ĭi l	ï	ĩ	ĭ	ĭ	ĭ

A. Description of original monument and accessories and/or subsequent restoration:

D/E-13: Meander Corner on the West side of Long Lake on the South line of Section 32, T47N-R27W. 1846: Austin Burt's original survey notes described the corner monument as a post referenced by: 10" White Pine N27 1/2E 14 1 1965: A survey of Section 33, T47N-R27W by Cleveland Cliffs Iron Company R.J. Brotherton in 1965 indicates he set the meander corner from a pine stump BT 714.15' West from the

calculated section corner in Long Lake. No corner accessories given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted a 3/4" iron pipe as M.C. referenced in Part "A" above. Distance West is 2091.36' to D-13 and distance East is 3384.89' to F-13.

> RATIFIED BY PEER GROUP P.A. 345 OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Replaced 3/4" diameter iron pipe with a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquatte County Survey Monument stamped to identify the corner referenced by nails in:

3" Spruce N69E 27.51 ft.

4 11 White Pine SS2E 9.65 ft.

Cedar S18W 11.40 ft.

S80W 37.28 ft.

Steel sign post NO9W 1.60 ft.

Monument is located 18' North of the waters edge and 38' West of the waters edge.

Bk. 5, Pg. 127

Levald W Carlson Signed by . Surveyor's Michigan License No. .

GERALD W CARLSON SURVEYOR No. 24589

PAR DE LABOREUNYS 🕏 JAN. 28, 1971 FORM APPROVED BY MICHIGAN STA REVISED MAY 14, 1975

REVISED JAN., 1983