

1993

COMMISSION

JOB NUMBER: 93300
SHEET NO. : 1-367
For corners in

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

<u>MARQUETTE</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>47N</u> R <u>24W</u>	<u>J-13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

LIBER 1 PAGE 63
Register of Deeds Stamp & File Number
MARQUETTE COUNTY
RECEIVED FOR RECORD
1993 DEC 29 AM 10:40
RECORDS OF DEEDS

I, GERALD W. CARLSON, in a field survey on Thursday, December 16, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

J-13: South Quarter Corner Section 35, T47N-R24W.
1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by:
10" Ironwood N50E, 23 l
6" Y.Birch N36W, 10 l

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Found a 3/4" pipe and old fence post with wire wrapped around it near found pipe. Projecting a line from the North 1/4 corner through the center 1/4 corner as shown on the recorded plat of Green Garden Hills falls approximately 20' East of the found iron pipe. Accepted iron pipe as corner. Peer group ratification 12-13-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Replaced existing marker with a 2 1/8" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:
9" Maple N35W 14.60 ft.
12" Maple N49E 23.56 ft.
5" Hemlock S16E 5.75 ft.
14" Maple N67W 21.52 ft.
Monument is 1.0 ft. above ground.
Bk. 4, Pg. 24



Signed by Gerald W. Carlson

Date 12-23-93

Surveyor's Michigan License No. 24589