

1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

JOB NUMBER: 93300

SHEET NO. : 1-369

For corners in

| MARQUETTE (County) | Located In: | Corner Code # |
|---------------------------------------|-------------------------|---------------|
| 1. Public Land Survey | T 47N R 24W | L-13 |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

REGISTER OF DEEDS
 MARQUETTE COUNTY
 RECEIVED FOR RECORD
 1993 DEC 29 AM 10:40
 1 PAGE 65
 Register of Deeds Stamp & File Number
 LIBER

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

I, GERALD W. CARLSON, in a field survey on Thursday, December 23, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

| | |
|--|---|
| L-13: South Quarter Corner Section 36, T47N-R24W. | 1962 - MDOT highway maps indicate a 1" iron pin referenced by |
| 1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by: | 4" Maple S80E 17.24 ft. |
| 5" Fir N57W, 6 l | 6" Maple N55E 11.58 ft. |
| 17" Y. Birch N51E, 27 l | 4" Maple W13.96 ft. |
| | Distance given to the Section Corner West 2630.23 ft. This corner is called common to Section 1, of T46N-R24W which is incorrect. |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Found 3/4" iron rod indicated as a found iron on William Donnan survey circa 1974. This iron rod is also indicated by Donnan as a North 1/4 corner of Section 1, which is incorrect. Distance West measures 2630.63, distance East measures 2631.47. The original call to the stream listed as 0.2 chains East of the corner apparently is incorrect. The stream measures 105 ft. East of the corner. The original notes found in the State Archives also indicate the stream 0.2 chains East of the corner. The distances between the corners check fairly good to G.L.O. (2640'). The stream call is apparently a mistake, in my opinion. Replaced 3/4" iron with a Marquette County Survey Monument. Peer group ratification 12-13-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Replaced found iron with a 2 1/8" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

| | | | |
|----------------|------|-----------|------------|
| 13" Maple | N62E | 11.08 ft. | Donnan NBT |
| 7" Maple | S74E | 17.15 ft. | |
| 9" White Birch | S05W | 10.57 ft. | Donnan NBT |
| 9" Maple | S89W | 14.06 ft. | |

Monument is 0.30 ft. above ground, 1 ft. East of old fence intersection bearing East, West and North. Monument is 3.54 ft. East of the North 1/4 corner of Section 1, T46N-R24W. Bk. 4, Pg. 79



Signed by Gerald W. Carlson Date 12-28-93

Surveyor's Michigan License No. 24589