REMONUMENTATION

MAY 2 2 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	COMMISSION

For corners in			
MARQUETTE (County)	Located In:	Corner Code #	-
1. Public Land Survey	·	30W	
Property Controlling in Section Miscellaneous Property in Sec.	s T	R	
4. Lot No, Reco	rded Plat		

(U	~ .
RECORDED _ Dec. 26, 1996	1
AT 4: 20 O'CLOCK P.M.	1
OF PAGE	Ì
(State a Glander	1
REGISTER OF DEADS	_
	-

1 MGE 373 1 IBER

Register of Deeds Stamp & File Number

in a field survey on NOVEMBER, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3 and 2 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3. Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

P.A. 345 OF 1990

A. Description of original monument and accessories and/or subsequent restoration:

Quarter Comer common to Sections 6 and 31, T47/48N - R30W

B-13:

1984; L.L.S. No. 30091 set a 1/2" capped rebar at proportionate distance between A-13 and E-13 on the township line witnessed by P.K. nails in: 14" Hemlock N30°E 15.40°; 6" Balsam S20°E 19.08°; 8" Spruce S55°E 19.18°; 14" Yellow Birch S75°W 14.53°. Recorded in L. 4R.C., Pg. 425.

1984; Corner shown on an unrecorded Certificate of Survey by Clark/Minard Land Surveys, Job No. 84-049. A review of this certificate and others by the same firm shows corners established essentially on a straight line from A-13 through E-13 to the meander corner G/H-13.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1996; ECI recovered 1/2" capped rebar. No original corner evidence or accessories recovered. The following measurements were taken to G.L.O. terrain calls: East "descend hill" ECI 384' - G.L.O. 372', "ascend hill" ECI 1347' - G.L.O. 1329', "over lake" (to West shoreline) ECI 1483' - G.L.O. 1416'; B-13: West "ascend hill" ECI 156' -G.L.O. 153', "descend hill" G.L.O. 1277' (indistinct call, broad transition area) "ascend hill" (felt to be descend hill) ECI 2268' - G.L.O. 2268'. Comer position established by acceptance of found capped rebar as a careful and faithful reestablishment of the position of the original corner. Distance East is 1478.06' and distance West is 2450.90'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

1996:

Replaced capped rebar with a 2-3/8" O.D. aluminum pipe capped with a 3-1/4" aluminum tablet Marquette County Survey monument stamped to identify the corner set about 0.7' above grade. Bearing trees are face, nail & butt blazed and painted yellow with B.T. tags attached. Butt blaze is scribed "B.T.". Three 1984 trees were utilized with distances measured from a duplex nail with an orange washer stamped "ECI-30097" in the side of the tree. Bearings are magnetic.

5" Balsam S53'E 19.10'; 21" Hemlock N29°E 15.29"; Such fence post with survey marker sign - South 1.2'.

10" Sprace S18'E 19.20';

6" Maple N36"W 11.44' (N.B.T.)

ALAN PIERCE LAND No. 30097

13

Signed by

Surveyor's Michigan License No._

30097

Date 12-19-96