

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| Marquette (County) | Located In: | Corner Code # |
|---------------------------------------|------------------|---------------|
| 1. Public Land Survey | T 48N R 29W | L5 |
| | T R | (GCDB 640500) |
| 2. Property Controlling in Section | S 12 T 48N R 29W | 3 |
| | S T R | (GCDB 600560) |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |
| 4. Lot No. , Recorded Plat | | |
| 5. Private Claims | | |

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

I, Stephan J. Szyszkoski, in a field survey on 10/13/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L5) Quarter corner common to Sections 12 and 13. 1848 - Established by Wells Burt, Deputy, midway and on the Section line between Section corners 40.02 chains east and west. Set Spruce post. Spruce 9" S81°E 21 links, Spruce 9" N52°W 3 links. Found no subsequent record.

(3-Sec. 12) North 1/16 corner between Sections 11 and 12. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L5) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2631.64' east and west.

(3-Sec. 12) Established the position for the corner midway and on the Section line between Quarter corner 1320.46' south and Section corner 1320.46' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Balsam N18°W 19.8' mrkd "1/4S NBT"
8" Balsam N37°E 14.85' do
5" W.Birch S03°E 9.9' do
6" Balsam S77°W 6.5' do
Set sq'd cedar post adjacent.
E= 7932823.093 N= 198351.836

(3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" Cedar N31°E 18.65' mrkd "1/4S BT"
3" Maple S18°E 13.45' do
4" Cedar S51°W 8.2' do
4" Cedar N54°W 7.15' do
Set sq'd cedar post adjacent.
E= 7932043.578 N= 199567.271

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/24/2014

For the Michigan Department of Natural Resources, Forest Resources Division

