

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 2 T 48N R 29W S _____ T _____ R _____ S 2 T 48N R 29W	7 (GCDB 600660) 6 (GCDB 560660)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 06/08/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(7-Sec. 2) North 1/16 corner between Sections 1 and 2. Not previously monumented.

(6-Sec. 2) Northeast 1/16 corner, Section 2. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(7-Sec. 2) Established the position for the corner 20 chains, proportionate to the original record, north of recorded 1/4 corner K2, and on the Section line between K1 1250.10' north and K2 1296.78' south.

(6-Sec. 2) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners. The position for the corner falls in Wolf Lake and was not monumented. Established a Witness Corner on the North 1/16 line 22.00' east of the corner position. The W.C. is 16.5' east of the water's edge of Wolf Lake.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Maple S24°W 7.85' mrkd "1/16S BT"
15" Cedar N40°W 11.0' do
4" Spruce N58°E 6.6' do
8" Maple N89°E 12.1' do
Set sq'd cedar post adjacent.
E= 7932051.488 N= 201164.238

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap
22.00' east of the position for the corner and on
the North 1/16 line. Set measuring nail with MDNR
tag in the side of:
8" Cedar N22°E 6.35' mrkd "WC BT"
4" Balsam S41°E 9.05' do
5" Maple S72°W 11.95' do
6" Cedar N88°W 4.35' do
Set sq'd cedar post adjacent.
E= 7931655.477 N= 201166.059 (the Wit. Cor.)

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski Date 06/17/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division