LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #	4 * *
1. Public Land Survey	T 48N R 30W	G3 (GCDB 400600)	e
2. Property Controlling in Section	S T R S T R	D3 (GCDB 240600)	
3. Miscellaneous Property in Sec.	S T R S T R		
4. Lot No. , Rec 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number 1 B C D E F G H I J K L M
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, recovered, found as expressed below:			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
A. Description of original monument and accessories and/or subsequent restoration:			
(G3) Corner common to Sections 3-4-9-10. 1848 - Established by Wells Burt, Deputy Surveyor. Set Spruce post. Spruce 14" N17°E 20 links, Spruce 10" S32°W 43 links. Found no subsequent record.			

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (G3) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner by double proportionate measurement to the original record between Section corner 5161.97 north (79.21 ch R); Quarter corner 2606.53' south (40.00 ch. R); Section corner 10,558.89' east (159.96 ch. R); and Quarter corner 2636.61' west (39.95 ch. R). The position for the corner falls in a swampy slough along the right bank of the W.Branch of the Peshekee River and could not be monumented. Established a WITNESS CORNER 118.00 ft. West of the corner position, on the Section line.

(D3) Quarter corner to Sections 5 & 8. 1992 - Remonumented and recorded by R.E.Schmeling PS 8317, from original GLO evidence. L5 R.C. Page 347. Set 1"x4' I.pipe with brass cap. Hard Maple 9" N39°E 38.0'; Y.Birch 16" S39°E 20.7'; Hard Maple 12" S31°W 8.2'; Hard Maple 11" N36°W 25.2'.

- (D3) Found the 1992 monument in good condition and at record bearing and distance from the 1992 witnesses: the Sugar N39°E is in good condition; the Sugar S31°W is a dead stub; the Y.Birch S39°E and Sugar N36°W are both dead and down. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap				
118.00' west of the corner position and on the				
Section line for a WITNESS CORNER. Set measuring				
nail with MDNR tag in the side of:				
8" B.Spruce S56°E 24.45' mrkd "WC BT"				
4" B.Spruce S20°E 11.0' do				
6" W.Spruce S79°W 5.0' do				
3" B.Spruce N60°W 19.25' do				
Set sq'd Cedar post adjacent.				
E= 7919179.373 N= 200062.276 (the Section cor.)				

Surveyor's Michigan Licerise No.

(D3) Found 1"ID I.pipe with brass MEAD CORP. cap, appropriately stamped. Set measuring nail with MDNR tag in the side of:

12" Sugar N42°E 37.9' old marks visible ('92 NBT)

3" Sugar N16°E 6.95'

mrkd "1/4S NBT"

3" Sugar N72°W 6.8' 3" Sugar N06°W 10.5'

ďo do

Set sq'd Cedar post adjacent.

E= 7916781.064 N= 200077.537

FORM APPROVED BY MICHIGAN STATE BOARD

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum

Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m. Signed by Date 11/12/2014

33986

STEPHAN J SZYSZKOSKI LAND SURVEYOR

For the Michigan Department of Natural Resources, Forest Resources Division